

smar  
FIRST IN FIELDBUS

FDI302

JUL / 10  
FDI302

OPERATION & MAINTENANCE  
INSTRUCTION MANUAL

## Fieldbus Communication Interface for Firmware Update



**smar**  
www.smar.com

**Specifications and information are subject to change without notice.  
Up-to-date address information is available on our website.**

**web: [www.smar.com/contactus.asp](http://www.smar.com/contactus.asp)**

# TABLE OF CONTENTS

<b>FDI302 - FIELDBUS COMMUNICATION INTERFACE FOR FIRMWARE UPDATE.....</b>	<b>5</b>
INTRODUCTION.....	5
CHARACTERISTICS .....	5
FUNCTIONAL DESCRIPTION.....	5
USED SIGNALS.....	5
TECHNICAL SPECIFICATIONS.....	5
OPERATION .....	6
FIELD DEVICES .....	6
DC302.....	8
<b>APPENDIX A - SRF – SERVICE REQUEST FORM.....</b>	<b>A.1</b>



# FDI302 - FIELDBUS COMMUNICATION INTERFACE FOR FIRMWARE UPDATE

## Introduction

The FDI302 Smar interface, (Fieldbus Communication Interface for Firmware Update), allows firmware update of the FOUNDATION™ fieldbus and PROFIBUS-PA field devices using a computer and Smar FBTools application software.

There are two models available:

**FDI302-1:** Fieldbus Communication Interface for Firmware Update - 302 and 303 series

**FDI302-2:** Fieldbus Communication Interface for Firmware Update - DC302

## Characteristics

- Compatible with all field devices of Smar 302 and 303 series, and also DC302;
- Powered by the computer, it does not need external power supply;
- Electrically isolated between the field device and the port EIA-232;
- Female DB9 standard serial connector;
- Easy and quick installation.

## Functional Description

Smar FDI302 allows firmware to be updated into field devices very quickly.

## Used Signals

**TxD** (Pin #3): TRANSMITTED DATA. Computer output signal and FDI302 interface input. This signal defines the serial data that will be transmitted. The nominal baud rate is 115200 bps.

**RxD** (Pin #2): RECEIVER DATA. Computer input signal and FDI302 interface output. This signal defines the serial data that will be read from the device. The nominal baud rate is 115200 bps.

**DTR** (Pin #4): DATA TERMINAL READY. Computer output signal and FDI302 interface input. This signal along with the RTS signal supplies the interface electronic circuit.

**RTS** (Pin #7): REQUEST TO SEND. Computer output signal and FDI302 interface input. This signal along with the DTR signal supplies the interface electronic circuit.

**GND** (Pin #5): SIGNAL GROUND. This signal is connected to the FDI302 interface circuit ground.

### NOTE

This ground is isolated from the field devices.

## Technical Specifications

TECHNICAL SPECIFICATIONS	
Communication Baud Rate	115200 bps (maximum)
Power Consumption	10 mA (maximum)
Electrical Isolation	1000 Vdc (typical)
Firmware Download Time	3 min (average)

## Operation

Any firmware of the Smar field devices, FOUNDATION fieldbus and PROFIBUS-PA, 302 and 303 series, besides the DC302 can be updated. The device must be connected and powered through the communication bus, or powered directly by a 24V power supply.

### Field devices

To update the firmware of field devices follow the steps below:

Attach the DB9 connector of the **FDI302-1** interface to the computer serial port, COM1 or COM2. Remove the front cover of field device that will receive the new firmware. If the field device has a display, it is not necessary to remove it.

Carefully attach the other end to the device interface according to figure 1 (this will freeze the device display).



**Fig. 1 – Interface Connected to the Device.**

Insert both guiding pins through the holes of the equipment's circuit board. Tighten on the screw, clockwise, until it is fixed. See figures 2 and 3.



Side view

Top view

**Fig.2 – FDI302-1's Connection Point with the Field Devices**




Fig. 3 – Field Device’s Connection Point with the FDI302-1

After fixing the interface and connecting it to the computer execute the FBTools Wizard program. The following figure will appear. Choose the device and click **Next**.




Fig. 4 – FBTools Wizard.

The following figure will appear. Choose the appropriate port (COM1 or COM2) and the firmware file (\*\*\*.ABS).




Fig.5 – FBTools Download.

Click **Download**. The program will erase the Flash memory and download the new firmware. For further details see the FBTools' manual. It can be obtained at Smar's website: [www.smar.com](http://www.smar.com)

**NOTE**

This process will take about 3 minutes to be concluded.

While "5" is lit on display, the device should not be turned off, because it indicates active EEPROM saving operation.

Once the download is finished, just turn off the device and remove the interface. Place the front cover to close it. Turn on the device, the display will show "init" message followed by "factory init" message.

## DC302

The procedure to update the firmware of DC302 is similar to that to the field devices. The appropriate interface is the **FDI302-2**.

Attach the DB9 connector of the **FDI302-2** interface to the computer serial port, COM1 or COM2. Remove the protective front cover of the DC302 that will receive the new firmware. See the following figure.



Top view

Connection's detail

Fig.6 – DC302's Connection Point with the FDI302

Carefully attach the other end to the device interface.





*Fig. 7 – FDI302-2's connection end for DC302*

Insert the two guiding pins through the holes of the equipment's circuit board. See the following figure.




*Fig. 8 – FDI302-2 connected to the DC302*

After fixing the interface and connecting it to the computer execute the FBTools Wizard program. The steps to be followed are the same done for the field devices.


While the “**Saving**” LED is lit on the device's frontal, it should not be turned off, because it indicates active EEPROM saving operation.

## Download Errors


During the download process, some errors may occur. When any error happens, the download process should be restarted. See following the causes of these errors:



Causes: the FDI302 interface may be not connected correctly or the device may be powered off.



Causes: the communication may be lost during the firmware download or the download process was not well performed.



Causes: the communication may be lost during the firmware download verification or a writing error in the flash memory occurred during the download process.

# Appendix A

<b>smar</b>	<b>SRF – Service Request Form</b>	
	<i>FDI302 - Fieldbus Communication Interface for Firmware Update</i>	Proposal N°: _____
<b>COMPANY INFORMATION</b>		
Company: _____		
Unit: _____		
Invoice: _____		
<b>COMMERCIAL CONTACT</b>		
Full Name: _____		
Phone: _____		Fax: _____
E-mail: _____		
<b>TECHNICAL CONTACT</b>		
Full Name: _____		
Phone: _____		Extension: _____
E-mail: _____		
<b>EQUIPMENT DATA</b>		
Model: _____		
Serial Number: _____		
<b>PROCESS DATA</b>		
Process Type (Ex. boiler control): _____		
Operation Time: _____		
Failure Date: _____		
<b>FAILURE DESCRIPTION</b>		
(Please, describe the failure. Can the error be reproduced? Is it repetitive?)		
_____		
_____		
_____		
_____		
<b>OBSERVATIONS</b>		
_____		
_____		
_____		
_____		
<b>USER INFORMATION</b>		
Company: _____		
Contact: _____		
Section: _____		
Title: _____		Signature: _____
Phone: _____		Extension: _____
E-mail: _____		Date: ____/____/____
For warranty or non-warranty repair, please contact your representative. Further information about address and contacts can be found on <a href="http://www.smar.com/contactus.asp">www.smar.com/contactus.asp</a> .		

